

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

IP1209
ENE
> 1
1.575 mi.
8317 ft.

VS 5425
E 19TH ST/VOORHIES AVE
BROOKLYN, NY

NY Spills S104788947
N/A

Site 3 of 4 in cluster IP

Relative:
Higher

Actual:
18 ft.

SPILLS:

Name: VS 5425
Address: E 19TH ST/VOORHIES AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0006415 / 2000-10-27
Facility ID: 0006415
Facility Type: ER
DER Facility ID: 79755
Site ID: 87006
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2000-08-30
Investigator: JHOCONE
Referred To: Not reported
Reported to Dept: 2000-08-30
CID: 389
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2000-08-30
Spill Record Last Update: 2000-10-27
Spiller Name: Not reported
Spiller Company: CON EDISON
Spiller Address: 4 IRVING PLACE
Spiller Company: 001
Contact Name: CALLER
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was O'CONNELL E2MIS NOTES: Reference spill #s: 0006418 and 0006421 Found in VS5425, transformer had leaked approx. 14 gallons of dielectric fluid onto 450 gallons of water. Appears to have migrated through ducts into VS5440, MH70613 and Line Hole MH69684. Update 8-30-00: Transformer is drained of all oil. Removed 225 gallons of oil with tanker. Loss of transformer oil 30 gallons. Oil and water pumped into VS5425 makes water, unable to shovel mud into barrels. Picked up mud with vactor. Double washed with Slix. Results returned as 9ppm PCB. Transformer replaced. No leaking equipment. Sump cleaned."

Remarks:

"caller reporting a spill of material from a faulty piece of equipment coned#133110 samples taken oil appears to have migrated into vs 5440 manhole 70613 manhole 69684 historical valve pcb is 7ppm on 9/23/97 tested. "

All Materials:

Site ID: 87006
Operable Unit ID: 827439
Operable Unit: 01
Material ID: 547533

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Material Code:	0541A
Material Name:	dielectric fluid
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	14.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported